


AMWFH-O

JAWS FOR EXTERNAL FORM HOLDING



★Key Point

Machinable jaws for AMWFH-WP

Part Number	D	d	H	H ₁	H ₂	M	M ₁	D ₁	T	Weight (kg)	Pneumatic Clamping Modules	Clamping Pins
AMWFH105-1200	120	25	56	45	20	M 8×20L Across Flats 5	M6×1	24	5	1	AMWFH105-WP	AMWFH105-M 8S
AMWFH140-1600	160	29	64	53	25	M12×25L Across Flats 8	M8×1.25	28	6	2.2	AMWFH140-WP	AMWFH140-M12S



Supplied With

- 1 of Locking Ring
- 1 of Hex Socket Button Head Screw

Technical Information

- Workpiece locating repeatability: ± 0.03
- Jaw locating repeatability: ± 0.02

Feature



- ① The central bottom part of the jaw is pulled down by supplying air to the turbo port.
- ② The 10 jaw sections tilt toward the center to clamp the external form of workpiece.


- The diaphragm clamping mechanism allows to clamp the workpiece securely with 10 jaw sections.
- Various shapes can be held.
- The allowable compression diameter is 0.6 mm, making it ideal for lost wax, die cast, extruded, drawn, and premachined workpieces.

How To Use

Jaw Mounting


1. Fix Clamping Pin

- Fix clamping pin with the furnished button head screw.



2. Mount on Clamping Module

- Supply air to the unclamping port and mount the jaw.
- Mount the jaw by inserting the round pin into the locating hole.




Jaw	Clamping Pin	Hex Wrench A	Hex Wrench B
AMWFH105-1200	AMWFH105-M 8S	Size 5	Size 6
AMWFH140-1600	AMWFH140-M12S	Size 8	Size 10

For mounting instruction of Clamping Module, see [AMWFH-WP](#) datasheet.


Jaw Machining

1. Set the locking ring in the jaw.


(Using a screw facilitates setting.)



2. Release air from the unclamping port and clamp the locking ring by spring force of the module. Remove the screw from the locking ring after clamping.




3. Machine the jaw to the contours of workpiece. Keep the machinable depth.




Workpiece Loading


1. Supply air to the unclamping port and remove the locking ring.



2. Load the workpiece and supply air to the turbo port.



Performance Curve



Note

Do not actuate clamping without a workpiece to avoid damage and deformation.