
R⊕\S Imao



Body / Clamp Arm / Piston	Clamping Spindle					
SCM440 steel Electroless nickel plated	S45C steel Quenched and tempered Electroless nickel plated					

★Key Point ———— Compact design!



	01 .	CI	amp	ing	Heigl	nt *)														
Part Number	Clamping Direction	Finished Surface Contact		ontact	Rough Surface Contact		s	L ₂	L ₁	W	L	H ₄	В	Dp	Н	D	W ₁	W ₂	H ₂	Ηı
	Direction	Min	. M	ax.	Min.	Max.														
AMWSW16R-W		20.5	. ,	39	33.5 40	40	1.2	37	45	65	30	12	8.4	48	85	30	16	8.4	18	50
AMWSW16L-W		32.5) 3	9		40														
AMWSW20R-W	CW	41.5			44 50.1	53.5	1.6	45	55	85	40	15	10.5	64	106	40	20	10.4	22	65
AMWSW20L-W	CCW) כ	51 4	44	55.5														
Part Number	М		Нз	D ₁	D ₂	Н₅	Lз	ŀ	H 6	Н7		eratir Pressu (MPa	ire	F	ampi orce N) **	Ŭ (Сар	ding acity) **)		eight g)
AMWSW16R-W AMWSW16L-W	M 8×1	.25	45.5	16	28	9	10		81	6		0.5~0.7		0.4			0.8		500	
AMWSW20R-W AMWSW20L-W	M10×1	.5	57	22	35	11	13	1	01	8] (0.65			1.3		1120	

^{*)} Clamping height can be adjusted within this range.

How To Use


■Setting Clearance between Workpiece

A clearance between clamping spindle and workpiece should be roughly half of the clamping stroke. The clamp arm swings horizontally.


Follow the steps below to adjust the clamping spindle to create proper clearance.



- Apply air to the unclamping port with an air blow gun to move the clamp to unclamping position.
- Rotate the arm manually to straight direction, and create an appropriate clearance to the workpiece.
 Putting a feeler gauge between the workpiece and the clamping spindle facilitates this setting.
- 3. Fix the clamping spindle with nuts.



Part No.	d (+0.2)	М	Р
AMWSW16-W	28	M 8×1.25	48
AMWSW20-W	35	M10×1.5	64



- ·Use clean air by removing moisture and debris with an air dryer and air filter.
- · Impurities in the compressed air can cause malfunction.

^{**)} The clamping force and the holding capacity above are at 0.5 MPa.